



- KEY
- LP Lamp Post
 - MH Manhole
 - UC Unidentified Cover
 - GU Gully
 - SS Station

- Tree
- Fence
- Top Of Bank
- Channel
- Kerb

Notes:

Please note that individual tree locations were not taken as the whole area is dense with vegetation and of a forest condition. The location of the top and bottom of the concrete weir feature was taken however the individual steps were cascading water with a severe slope to either side making it dangerous to get to.

All information contained in this survey is correct at the time of undertaking but should be checked prior to use.

Issue	File Type	Destination		Date	Approved										
Rev	Revision Date	Purpose of revision	Drawn	Checked	Approved										
<div><div></div><div></div></div> <p>Angie Astley, Assistant Director of Customer & Neighbourhood Services, Darby House, Telford, TF3 4JA</p> <p>Project</p> <p>Brick Kiln Bank</p> <p>Drawing title</p> <p>3D Topographical Survey With Levels</p> <table><tr><td>Scale 1:500</td><td>A2</td><td>Date 14/05/2018</td><td>Drawn-by NAH</td><td>Checked-by GP</td></tr><tr><td colspan="4">Drawing number LP499/01</td><td>Rev 0</td></tr></table>						Scale 1:500	A2	Date 14/05/2018	Drawn-by NAH	Checked-by GP	Drawing number LP499/01				Rev 0
Scale 1:500	A2	Date 14/05/2018	Drawn-by NAH	Checked-by GP											
Drawing number LP499/01				Rev 0											